

Attachment 2 – Storm Drain & Sink Hole Damage (2850 Sneath Lane)



Sink hole at 2850 Sneath Lane



Bottom of the pipe missing (lower section)



Upper areas of damaged pipe (from behind the retaining wall up to the manhole in the back yard of 2765 Sneath

